My new 997.1 engine has rubbing in cylinder

Beitrag von „Frage -> Antwort“ vom 18. Juli 2022, 08:56

Morning Jurgen,

Thanks for that. I presume the cost is in Euros?

8000 euros for a standard rebuild with nothing else required bar new cylinders and pistons..

How long would it usually take to complete the work?

Do you have a cost for fitting the X51 Kit?

Kind regards,

Tim