

My new 997.1 engine has rubbing in cylinder

Beitrag von „Frage -> Antwort“ vom 15. Juli 2022, 06:51

Hello,

I have just found your website after browsing the net.
I found the Carrera to GT3 conversion story very interesting.

I had a new engine rebuilt by Porsche Belfast in 2014 at 50000 miles. (All done under extended warranty)

My new engine has been running for 30,000 miles and now has a little rubbing in cylinder 1. Oil consumption is still normal and exhaust tips clean.

I would be very keen to hear your thoughts on upgrade options.

Kind regards,

Tim