

Porsche 997 Carrera the yellow engine warning light comes on.

Beitrag von „Albert Motorsport“ vom 4. April 2022, 09:18

A dear customer contacts us and explains that a yellow engine light suddenly comes on after washing the car.

What can we do?

Unfortunately, he has to come to our company with the car so that we can precisely analyze the defect.


He brings us the car and we start the analysis and work in the following order.

After a few minutes, the damage is localized and repaired.

Porsche 997 Carrera die gelbe Motor Warnlampe leuchtet auf.



Porsche 997 Carrera die gelbe Motor Warnlampe leuchtet auf.



Porsche 997 Carrera die gelbe Motor Warnlampe leuchtet auf.

Scope of order:

- Troubleshooting, the yellow warning lamp lights up
- Prepare a cost estimate after assessing the damage

Extent of damage:

- Lambda sensor defective

Repair history:

- Vehicle - let the engine run
- Connect the electronics to the Porsche Piwis system
- Read all error codes
- Stop engine
- Erase all error codes
- run the engine again
- Evaluate new error codes
- Determination: Lambda probe defective
- Order Lambda probe

Next steps:

- Replace lambda probe
- test drive the vehicle
- make a bill
- Deliver the vehicle to the customer.
- Have a happy customer again!