

My new 997.1 engine has rubbing in cylinder

Beitrag von „Frage -> Antwort“ vom 18. Juli 2022, 07:44

Hi Jurgen,

That's great, thanks for the explanation and advice.

Could I use my existing pistons in the new Graphite Cylinders or is it advised to change them all?

Or is it just the piston rings you need to change?

What else usually needs replaced? If as in my case the engine is still running well.

Also, is it possible to opt for the X51 power upgrade with this method or would you advise against this...

The last thing is price and lead time to do the work. Would it have to be done in Germany by yourself

or can the parts be shipped and fitted by a porsche specialist in the UK/Ireland?

Kind regards,

Tim